

M.aterial S.afety D.ata S.heet

Product Name:

Blue Glass – Anti Marking Films

General Description:

Polyethyleneterephthalate films coated with Acrylic Resin and Glass Beads, of various thicknesses (between .006” (260 gsm) and .032” (540 gsm), colors, and can have an adhesive-receptive surface on one surface.

1. Hazardous Ingredients:

The above product(s) are considered “articles” according to OSHA Hazard Communication Standard 29 CFR 1910.1200 and, as such are exempt from the material safety data sheet provisions of 29 CFR 1910.1200 (G) (6). As a courtesy to the customer, Printing Research Inc. has prepared this material safety data sheet to provide appropriate safety and handling information. These products are considered non-hazardous when used according to accepted practices for the intended use.

2. Physical/Chemical Data:

Appearance and Odor: Flexible, orderless sheets, various shades of white, off-white, blue, black or other colors

Solubility in Water: Insoluble

3. Fire & Explosion Hazard Data:

Flash Point: N/A

Extinguishing Media: Water spray, foam, dry chemical

Special Fire Fighting Procedures:

Wear face mask and self-contained breathing apparatus approved by the U.S. Bureau of Mines if there is a danger of inhaling smoke from a fire involving any polyethyleneterephthalate

Unusual Fire and Explosion Hazards:

N/A

4. Reactivity Data:

Stability: Stable under normal conditions

Hazardous Decomposition or by-products:

N/A

M.aterial S.afety D.ata S.heet

5. Health Hazard Data:

Routes of entry:

N/A

Health Hazards (Acute and Chronic):

No significant hazards

Signs and Symptoms to Exposure:

No significant hazards

6. First Aid:

Emergency First Aid Treatment:

Eye Contact: Gently rinse affected eye(s) with clean water

Skin Contact: Wash with water

Inhalation: Remove patient to fresh air; call physician

Ingestion: Rinse mouth with water; call physician

7. Precautions for Safe Handling and Use:

Steps to be taken in case material is released or spilled: N/A

Waste Disposal: Dispose of product in accordance with national and/or local regulation

Precautions to be taken in handling and storing: Provide proper local and general ventilation out of direct sunlight or water. Avoid contamination of smoking materials; do not smoke while cutting, heat sealing or fabricating material. Handle with care, do not scratch and break. Rolls should be suspended (by bracket) to refrain rolls from direct contact with ground

For Additional Information Contact:

Printing Research Inc.
10954 Shady Trail
Dallas, Texas 75220 USA
214-353-9000 (Telephone)
214-357-5847 (Fax)